

Illinois State University

Asbestos Containing Building Material Summaries

302 Normal St. (HHN)	2
Bone Student Center (BON)	2
Carter Harris Physical Plant Shop (PPO).....	3
Centennial West (CW).....	3
Centennial East (CE)	4
Center for the Visual Arts (CVA).....	4
Cook Hall (CH)	4
DeGarmo Hall (DEG).....	5
Edwards Hall (EDW)	5
Felmley Hall of Science (FHS)	5
Felmley Science Annex (FSA)	6
Golf Course Maintenance (GC)	6
Golf Pro Shop (GC)	7
John Green Food Service Building (GFS)	7
Heating Plant (HPT).....	7
Hewett Hall (HEW)	8
Horton Fieldhouse (HTN)	8
Hovey Hall (HOV)	9
Instructional Technology and Development Center (ITDC)	10
Julian Hall (JH)	10
Marketplace at Linkins Center (LIN).....	10
Manchester Hall (MAN)	11
Milner Library (MLB)	11
Moulton Hall (MLT)	11
Nelson Smith Building (NSB)	12
Old Union (OU).....	12
Ropp Agriculture Building (RAB)	13
ROTC Building (HUA).....	13
Schroeder Hall (SCH)	13
Shelbourne Apartments/Laundry Building (SDU)	13
Stevenson Hall (STV)	14
Student Accounts Building (SAB)	14

Turner Hall (TUR)	14
Vitro Center (Glass House) (VIT)	14
Vrooman Center (VRO)	14
Watterson Dining Commons (WDC)	14
Watterson Towers North and South (WTN/WTS)	15
Tri Towers/West Campus.....	15
Haynie Hall (HAY), Wilkins Hall (WIL), Wright Hall (WRT).....	15
Williams Hall (WIH)	15

302 Normal St. (HHN)

Homogenous Area	Description	Location
9x9 floor tile	9"x9" floor tile, white	Throughout building
Black mastic	Adhesive under white 9"x9" floor tile	Throughout building
Drywall mud	Drywall joint compound	Throughout building

Bone Student Center (BON)

Homogenous Area	Description	Location
Texture on Plaster Ceilings	Acoustical finish on plaster	183, 184, 223, 228
Tank insulation	Insulation on hot water tanks, steam pressure vessels and equipment	Mechanical rooms, kitchen
Fitting insulation	Hard insulation on pipe fittings-domestic water, plumbing drains, steam, hot water heat	Mechanical rooms, ceiling spaces, pipe chases, behind walls
Mag block pipe insulation	Hard pipe insulation on steam lines	Mechanical rooms, ceiling spaces, pipe chases, behind walls
Gasket material	Not described other than beige in color	Mechanical rooms
12x12 floor tile	Classic cream w/olive	Brown Ballroom
12x12 floor tile	Olive w/white and dark olive chip	Brown Ballroom
Black mastic	Mastic beneath 12x12 floor tile	Brown Ballroom
Tar coating on ductwork	Black tar	Mechanical rooms and building HVAC ductwork
Fire curtain	Stage curtain	Brown Ballroom
Paper backing on lights	Paper backing insulation on original light fixtures	Building wide
Transite	Concrete like concrete panels	Kitchen ovens

Carter Harris Physical Plant Shop (PPO)

Homogenous Area	Description	Location
Layered paper pipe insulation	Cardboard like paper insulation on piping	Mechanical rooms, pipe chases, ceiling spaces, behind walls and in exposed areas
Fitting insulation	Hard mud like insulation on pipe fittings(fiberglass and layered paper insulated pipes)	Mechanical rooms, pipe chases, ceiling spaces, behind walls and in exposed areas
Tank insulation(mag block)	Insulation on hot water tanks, steam pressure vessels and equipment	Mechanical rooms
9x9 floor tile	9"x9" floor tile, tan	Could be found throughout building(some could be located under carpeting)
12x12 floor tile	12"x12" floor tile, gray w/ black marbling	Could be found throughout building(some could be located under carpeting)
Carpet mastic*	Adhesive under original carpeting	Wherever carpeting is found
Flange gasket*	Original gaskets in pipe flanges	Mechanical rooms
Fire door insulation*	Insulation encased in fire rated doors	Could be found throughout building

*CDB asbestos building inspection report did not include sampling of these materials and it is unknown if they still exist. They were assumed to be positive by CDB. If materials remain and will be disturbed, further sampling will be needed.

Centennial West (CW)

Homogenous Area	Description	Location
Fitting insulation	Hard mud material on fiberglass, tar paper, and foam insulated piping	Mechanical rooms, pipe chases, above ceilings, behind walls
Mag block pipe insulation	hard insulation on piping	Mechanical rooms, pipe chases, above ceilings, behind walls
Tar paper insulation	Black, tar like insulation on piping	Mechanical rooms, pipe chases, above ceilings, behind walls
Hot water tank insulation	Hard thermal system insulation material	Mechanical rooms
9x9 floor tile	All 9x9" floor tile	Classroom and office spaces
12X12 floor tile	All original/order 12x12" floor tiles	Classroom and office spaces
Black mastic	Black adhesive under 9x9 and 12x12 floor tiles	Classroom and office spaces
Paper backing on lights	Paper insulation in light fixtures	Original hallway lighting

Centennial East (CE)

Homogenous Area	Description	Location
Fitting insulation	Hard mud material on fiberglass, tar paper, and foam insulated piping	Mechanical rooms, pipe chases, above ceilings, behind walls
Mag block pipe insulation	hard insulation on piping	Mechanical rooms, pipe chases, above ceilings, behind walls
Tar paper insulation	Black, tar like insulation on piping	Mechanical rooms, pipe chases, above ceilings, behind walls
Hot water tank insulation	Hard thermal system insulation material	Mechanical rooms
9x9 floor tile	All 9x9" floor tile	Classroom and office spaces
Black mastic	Black adhesive under 9x9 and 12x12 floor tiles	Classroom and office spaces
Paper backing on lights	Paper insulation in light fixtures	Original hallway lighting

Center for the Visual Arts (CVA)

Homogenous Area	Description	Location
Spray on acoustical ceiling	Textured finish on ceiling plaster	Rooms 145 to 152 and 177 to 179
Hot water tank insulation	Hard thermal system insulation	Mechanical rooms
Converter insulation	Heat exchanger insulation	Mechanical rooms
Condensate return assembly insulation	Heat exchanger insulation	Mechanical rooms
Fitting insulation Note: negative samples but material is treated as ACM	Hard insulation on pipe fittings. Domestic water, steam, hot water heat, drain lines	Mechanical rooms, pipe chases,
12x12 floor tile	"older" Tan floor tiles	Throughout building
Floor tile mastic	Black mastic under 12x12 tiles	Throughout building (under older 12x12 floor tiles)
Paper backing on lights	Insulation on original building light fixtures	Throughout building
Transite	Concrete like sheeting	Hoods and ovens in art lab spaces
Oven insulation	Described only as tan/gray in color. **Friable material**	On top of large oven in art lab space

Cook Hall (CH)

Homogenous Area	Description	Location
Black mastic	Black adhesive under 12x12 floor tiles	Under any 12x12 FT throughout building

DeGarmo Hall (DEG)

Homogenous Area	Description	Location
12x12 Floor tile	Tan 12x12" floor tiles	Throughout building. *many areas have been abated. Some may exist under carpeting
Black mastic	Adhesive under 12x12 tiles	Throughout building where original 12x12 floor tiles exist
Mag block pipe insulation	Hard, white insulation on piping	Mechanical rooms, pipe chases, ceiling spaces, behind walls
Hot water tank insulation	Hard, white insulation on tanks	Mechanical rooms
Heat exchanger insulation	Hard, white insulation on heat exchanger	Mechanical rooms
Condensate return assembly	Hard, white insulation on return assembly	Mechanical rooms
Fitting insulation	Hard, beige insulation on pipe fittings	Mechanical rooms, pipe chases, ceiling spaces, behind walls
Gaskets in floor heaters	White, gasket like insulation	Steam line penetrations on heat perimeter units on floors 2-5.

Edwards Hall (EDW)

Homogenous Area	Description	Location
Fitting insulation	Hard mud insulation on fiberglass pipe insulation	Capen stage, mechanical rooms, pipe chases, behind halls

NOTE: Edwards Hall has undergone major renovations that have eliminated most asbestos containing material. However, abatement projects may not have involved demolition to some walls, chases and other inaccessible areas. Caution should be demonstrated when penetrating walls.

Felmley Hall of Science (FHS)

Homogenous Area	Description	Location
Aircell pipe insulation	Cardboard like insulation on piping and ductwork	Mechanical rooms, pipe/duct chases, above ceilings, behind walls
Mag block pipe insulation	Hard, white insulation on piping	Mechanical rooms, pipe/duct chases, above ceilings, behind walls
Layered paper pipe insulation	Cardboard like insulation on piping	Mechanical rooms, pipe/duct chases, above ceilings, behind walls
Rope insulation	White gasket like insulation	Steam pipe penetrations inside perimeter heat units

12x12 floor tile	Tan 12x12" floor tile	Classrooms, hallways and offices
9x9 floor tile	Description unknown	Classrooms, hallways and offices
Black mastic	Black adhesive under floor tiles	Under 12x12 and 9x9 tiles
Lab tables	Black composite lab tops, sinks	Laboratories
Transite	Concrete like sheeting	Fume hoods

Felmley Science Annex (FSA)

Homogenous Area	Description	Location
Fitting insulation	Hard fitting insulation material on fiberglass insulated piping	Mechanical rooms, pipe chases, above ceilings and behind walls
Hot water tank and exchanger insulation	Off white, hard insulation on water tanks and heat exchangers	Mechanical rooms
Layered paper pipe insulation	Beige paper pipe insulation	Mechanical rooms, pipe chases, above ceilings and behind walls
Duct insulation	Off white insulation	Mechanical rooms, pipe chases, above ceilings and behind walls
Rope insulation	White gasket like insulation	Steam pipe penetrations inside perimeter heat units
9x9 floor tile	"older" beige/white/brown 9x9" floor tile	Throughout building
12x12 floor tile	"older" tan/brown 12x12" floor tile	Throughout building
Black mastic	Black adhesive under "older" 9x9 and 12x12 floor tile	Throughout building
Transite	Concrete like sheeting	Inside fume hoods
Transite sheeting	Concrete like sheeting	Mechanical rooms
Transite tables	Concrete like sheeting	Tables in greenhouse
Spray on acoustical ceiling	Textured finish on plaster	Mechanical room ceiling, sub ceiling

Golf Course Maintenance (GC)

Homogenous Area	Description	Location
Sheet flooring	Linoleum type sheet flooring	Unknown
Sheet flooring mastic	Adhesive under sheet flooring	Unknown
12x12 floor tile	Original 12"x12" floor tile	Unknown
12x12 floor tile mastic	Adhesive under 12x12 floor tile	Unknown

NOTE: CDB inspection did not include sampling of these materials and it is unknown if they still exist. They were assumed to be positive by CDB. If materials remain and will be disturbed, further sampling will be needed.

Golf Pro Shop (GC)

Homogenous Area	Description	Location
Sheet flooring	Linoleum type sheet flooring	Unknown
Sheet flooring mastic	Adhesive under sheet flooring	Unknown
Carpet mastic	Adhesive under carpeting	Unknown

NOTE: CDB inspection did not include sampling of these materials and it is unknown if they still exist. They were assumed to be positive by CDB. If materials remain and will be disturbed, further sampling will be needed.

John Green Food Service Building (GFS)

Homogenous Area	Description	Location
Fitting Insulation	Grey, hard mud like insulation on pipe fittings	Mechanical rooms, pipe chases, above ceilings, behind walls, openly exposed
Tank insulation	Gray, hard mud like insulation on tanks and pressure vessels	Mechanical rooms
Air cell pipe insulation	Tan, cardboard like insulation on piping	Mechanical rooms, pipe chases, above ceilings, openly exposed, behind walls
Spray on acoustical ceiling	White, textured(popcorn) finish on hard plaster ceilings	Office area ceilings
9x9 floor tile	Tan 9"x9" floor tile	Throughout building *could be located under carpeting
9x9 floor tile mastic	Black adhesive under 9x9 floor tile	Anywhere 9x9 floor tile is located
Transite panels	Gray, concrete like sheeting	Ceiling above small kitchen, lower exterior of building

Heating Plant (HPT)

Homogenous Area	Description	Location
*Boiler insulation	Hard insulation on boilers	Boiler room
Mag block pipe insulation	Hard insulation on steam lines	Throughout building
Fitting insulation on mag block	Hard mud like insulation on pipe fittings	Throughout building
Layered paper pipe insulation	Cardboard like insulation on piping	Throughout building
Fitting insulation on layered paper	Hard mud like insulation on pipe fittings.	Throughout building
Aircell pipe insulation	Cardboard like insulation on piping, tanks, pressure vessels	Throughout building
Fitting insulation	Hard mud like insulation on fittings- fiberglass insulated pipes	Throughout building

Pipe wrap	Black tar paper on pipe insulation	Throughout building
**12x12 floor tile	"older" 12"x12" floor tile	Office and break areas
**Black mastic	Black adhesive under 12x12 tiles	Office and break areas
**Flange gaskets	Original gaskets on boiler	boilers
**Fire door insulation	Insulation inside fire doors	boilers
**Flexible duct connector	Original duct connector	Ductwork and boilers
**Transite conduit	Concrete like pipe conduit	Throughout building

*Consult with ISU Environmental Health and Safety before disturbing any insulation on the boilers. Most asbestos insulation is either negative or has been abated but some asbestos remains in specific areas.

**CDB inspection did not include sampling of these materials and it is unknown if they still exist. They were assumed to be positive by CDB. If materials remain and will be disturbed, further sampling will be needed.

Hewett Hall (HEW)

NOTE: Building wide abatement has been completed to remove all ACM materials. However, if insulation materials other than fiberglass or armaflex(foam) are discovered in mechanical rooms, pipe chases, above ceilings or behind walls, stop work and contact the ISU Project Manager.

Horton Fieldhouse (HTN)

Homogenous Area	Description	Location
Layered paper insulation	Cardboard like insulation on piping	Mechanical rooms, pipe chases, ceiling spaces, behind walls, and openly exposed
Fitting insulation	Hard mud like insulation on pipe fittings	Mechanical rooms, pipe chases, ceiling spaces, behind walls, and openly exposed
Tank insulation	Hard, mud like insulation on tanks and pressure vessels	Mechanical rooms
*9x9 floor tile	9"9" floor tile(various colors)	Classrooms, hallways, and office spaces
*12x12 floor tile	"Original"12"x12" floor tile(various colors)	Classrooms, hallways, and office spaces
*Black mastic	Black adhesive under 9x9 and 12x12 floor tile	Classrooms, hallways, and office spaces
*sheet vinyl	Sheet flooring	Unknown(may have been abated)
*Carpet mastic	Adhesive under older carpeting	Classrooms and offices
*Flange gasket	White, gray gasket material between pipe flanges and joints	Mechanical rooms, pipe chases, ceiling spaces, behind walls, and openly exposed

*Rubber floor mastic	Adhesive under rubber flooring	Locker rooms, classrooms and anywhere original rubber flooring exists
*Fire door insulation	Insulation inside fire doors	Throughout building
*Transite duct	Concrete like duct	Mechanical rooms, chases, above ceilings

* CDB asbestos building inspection report did not include sampling of these materials and it is unknown if they still exist. They were assumed to be positive by CDB. If materials remain and will be disturbed, further sampling will be needed.

Hovey Hall (HOV)

Homogenous Area	Description	Location
Fitting insulation	Hard mud like insulation on pipe fittings	Mechanical rooms, pipe chases, ceiling spaces, behind walls on floors 2-4
Circulating tank insulation	Hard mud like insulation on tanks and pressure vessels	Mechanical rooms
Mag block pipe insulation	Gray/white, hard insulation material on piping	Mechanical rooms, pipe chases, ceiling spaces, behind walls on floors 2-4
Layered paper pipe insulation	Cardboard like paper insulation on piping	Mechanical rooms, pipe chases, ceiling spaces, behind walls on floors 2-4
Duct insulation(air cell)	Gray corrugated insulation on ductwork	Mechanical rooms, chases, above ceilings on floors 2-4
Insulation behind floor heater units	Paper insulation	All perimeter convector units on floors 2-4
Insulation behind doors on ductwork	"sticky" paper insulation on inside of inspection doors in ductwork	Mechanical rooms, chases, above ceilings on floors 2-4
9x9 floor tile	All 9"x9" floor tile(red, brown, black)	Floors 2-4(may be located under carpeting)
12x12 floor tile	Original 12"x12" floor tile(brown)	Floors 2-4(may be located under carpeting)
Floor tile mastic	Black tile adhesive under 9x9 and 12x12 floor tiles	Floors 2-4(may be located under carpeting)
Paper backing on lights	Gray paper insulation	Original can light fixtures on floors 2-4
Light wiring	Wire insulation on light fixture whips	Original can light fixtures on floors 2-4
Fireproofing	White spray on fireproofing on decking	Above the S-2 fan in Annex basement mechanical room

Instructional Technology and Development Center (ITDC)

Homogenous Area	Description	Location
12x12 tile	12"x12" floor tile, brown w/white marbling	Throughout building. Some may be located under carpeting
Black mastic	Adhesive under 12"x12" floor tile and original/older carpeting	Throughout building. Some floor tile and mastic may be located under carpeting

Julian Hall (JH)

Homogenous Area	Description	Location
Fitting insulation	Hard mud like insulation on pipe fittings	Mechanical rooms, pipe chases, ceiling spaces, behind walls
Heat exchanger insulation	Hard mud like insulation on heat exchanger	Mechanical rooms
Mag block pipe insulation	Gray/white, hard insulation material on piping	Mechanical rooms, pipe chases, ceiling spaces, behind walls
9x9 floor tile	9"x9" imperial fleece white floor tile	Throughout building(may be under carpeting)
12x12 floor tile	12"x12" tan, beige floor tile	Throughout building(may be under carpeting)
Floor tile mastic	Black tile adhesive under 9x9 and 12x12 floor tiles	Throughout building(may be under carpeting)
Black tar coating	Tar coating on ductwork	Above ceilings on the first floor
Transite wall panels	Concrete like paneling	Office walls/half walls *all may have been removed but this is not confirmed

Marketplace at Linkins Center (LIN)

Homogenous Area	Description	Location
Fitting insulation	Hard mud like insulation on pipe fittings(on fiberglass and layered paper insulated pipes)	Mechanical rooms, pipe chases, ceiling spaces, behind walls
Layered paper insulation	Cardboard like layered paper insulation on piping	Mechanical rooms, pipe chases, ceiling spaces, behind walls
Mag block(magnesium) tank insulation	Hard mud like insulation on tanks and pressure vessels	Mechanical rooms

Note: The dining center underwent a major renovation to include the asbestos containing materials. Some materials remain in the mechanical rooms and caution should be used when penetrating walls in the dining center in case some materials were missed during abatement.

Manchester Hall (MAN)

NOTE: Building wide abatement has been completed to remove all ACM materials. However, if insulation materials other than fiberglass or armaflex (foam) are discovered in mechanical rooms, pipe chases, above ceilings or behind walls, stop work and contact the ISU Project Manager.

Milner Library (MLB)

Homogenous Area	Description	Location
Fitting insulation*	Hard mud like insulation on pipe fittings	Mechanical rooms, pipe chases, ceiling spaces, behind walls and in exposed areas
Elevator brake shoe**	Hard, metallic brake shoe for elevator operation	Elevator shaft
Flange gasket**	White/gray gasket material between pipe flanges	Mechanical rooms, pipe chases, and anywhere flanged components are located
Fire door insulation**	Foam like insulation in the core of fire rated doors	Throughout facility
12x12 floor tile**	12"x12" floor tile, beige	Some areas of the first floor (could be under carpeting), janitor closets on all floors.

*Bulk sample history for this building has indicated that fitting insulation is not asbestos containing. However, this type of material and vintage industry wide is rarely negative. The University considers the material suspect and treated as asbestos containing unless area specific sampling is done to determine content.

**CDB asbestos building inspection report did not include sampling of these materials and it is unknown if they still exist. They were assumed to be positive by CDB. If materials remain and will be disturbed, further sampling will be needed

Moulton Hall (MLT)

Homogenous Area	Description	Location
Air Cell pipe insulation	Grey, hard mud like insulation on pipe fittings	Mechanical rooms, pipe chases, above ceilings, behind walls, openly exposed on floors 2-3
Mag block pipe insulation	Gray/white, hard insulation material on piping	Mechanical rooms, pipe chases, above ceilings, behind walls, openly exposed on floors 2-3
Layered paper pipe insulation	Cardboard like paper insulation on piping	Mechanical rooms, pipe chases, above ceilings, behind walls, openly exposed on floors 2-3
12x12 floor tile	Brown/beige 12"x12" floor tile	Classrooms, offices, BSW closets on floors 2-3. *may be located under carpeting

9x9 floor tile	Unknown color 9"x9" floor tile	Classrooms, offices, BSW closets on floors 2-3. *may be located under carpeting
Black mastic	Black floor tile adhesive	Under 12"x12" and 9"x9" floor tile.

Note: Moulton Hall underwent a major renovation to include most asbestos containing materials. However, some materials may remain in the mechanical rooms, pipe chases and other areas inaccessible during abatement. Caution should be used when penetrating walls and ceilings, accessing pipe chases and working in mechanical rooms

Nelson Smith Building (NSB)

Homogenous Area	Description	Location
Fitting insulation	Hard mud like insulation on pipe fittings	Mechanical rooms, pipe chases, ceiling spaces, behind walls, exposed piping
Hot water tank insulation	Hard mud like insulation on hot water tank	Mechanical rooms
Heat exchanger insulation	Hard mud like insulation on hot water tank	Mechanical rooms
9x9 floor tile	9"x9" floor tile, maple wood grain	Offices, hallways, storerooms, bathrooms. *some tiles could exist under carpeting
12x12 floor tile	12"x12" floor tile, Iroquois tan	Offices, hallways, storerooms, bathrooms. *some tiles could exist under carpeting
Black mastic	Adhesive under 9"x9" and 12"x12" floor tile	Offices, hallways, storerooms, bathrooms. *some tiles could exist under carpeting
Paper backing on globe lights	Thermal insulation paper around socket of fixture	Unknown(may have all been removed)
2x4 ceiling tiles	2"x4" suspended ceiling tile	Hallways, offices, storerooms on floors 1-2 *consult with ISU EHS before moving ceiling tile

Old Union (OU)

Homogenous Area	Description	Location
Spray on acoustical ceiling	Textured finish on ceiling plaster	206, 207, 207A, 209, 211, 309, 309A/B, 310B(some ceilings are exposed, some are above suspended ceilings)
Flexible duct connector	Gray or black colored canvas material on ductwork	Mechanical rooms and on older ductwork throughout building
9x9 floor tile*	Original 9"x9" floor tile	Stairwells on floor 1 and in several areas on floors 2 and 3

		(may be located under carpeting)
12x12 floor tile*	Original 12"x12" floor tile	Stairwells on floor 1 and in several areas on floors 2 and 3 (may be located under carpeting)
Carpet mastic*	Adhesive under original carpeting	Could possibly be found on any floor
Flange gasket*	Original gaskets in pipe flanges	Mechanical rooms

* CDB asbestos building inspection report did not include sampling of these materials and it is unknown if they still exist. They were assumed to be positive by CDB. If materials remain and will be disturbed, further sampling will be needed.

Note: Old Union underwent a major renovation to include most asbestos containing materials other than the spray on acoustical ceilings in the listed areas. However, some materials may remain in the mechanical rooms, pipe chases and other areas inaccessible during abatement. Caution should be used when penetrating walls and ceilings, accessing pipe chases and working in mechanical rooms.

Ropp Agriculture Building (RAB)

Homogenous Area	Description	Location
12x12 floor tile	12"x12" floor tile-black, tan	Throughout building
Black mastic	Black adhesive under 12"x12" floor tiles	Throughout building
Transite sheeting	Concrete like sheeting	Above drop ceiling in corridors

ROTC Building (HUA)

Homogenous Area	Description	Location
9x9 floor tile	9"x9" floor tile, brown	Basement
Linoleum	Linoleum sheet flooring, brown	basement

Schroeder Hall (SCH)

NOTE: Building wide abatement has been completed to remove all ACM materials. However, if insulation materials other than fiberglass or armaflex (foam) are discovered in mechanical rooms, pipe chases, above ceilings or behind walls, stop work and contact the ISU Project Manager.

Shelbourne Apartments/Laundry Building (SDU)

Homogenous Area	Description	Location
12x12 floor tile	12"x12" floor tile, brown/beige	Apartment units, laundry building
Black mastic	Adhesive under 12"x12" floor tile	Apartment units, laundry building

Stevenson Hall (STV)

NOTE: Building wide abatement has been completed to remove all ACM materials. However, some pipe insulation may remain in pipe chases and other areas that would have required demolition to access the asbestos materials. If insulation materials other than fiberglass or armaflex (foam) are discovered in mechanical rooms, pipe chases, above ceilings or behind walls, stop work and contact the ISU Project Manager. Caution should be used when penetrating and/or demolishing walls.

Student Accounts Building (SAB)

Homogenous Area	Description	Location
12x12 floor tile	12"x12" floor tile	Throughout building(could be located under carpeting)
Mastic under 12x12 floor tile	Black adhesive under 12"x12" floor tile	Throughout building(could be located under carpeting)

Turner Hall (TUR)

NOTE: Building wide abatement has been completed to remove all ACM materials. However, some pipe insulation may remain in pipe chases and other areas that would have required demolition to access the asbestos materials. If insulation materials other than fiberglass or armaflex (foam) are discovered in mechanical rooms, pipe chases, above ceilings or behind walls, stop work and contact the ISU Project Manager. Caution should be used when penetrating and/or demolishing walls.

Vitro Center (Glass House) (VIT)

Homogenous Area	Description	Location
2x4 ceiling tiles	2"x4" suspended ceiling tile	Room 103(glass work room, South entrance area.
Transite sheeting	Concrete like sheeting	Wall panels around kilns, on kilns
Tape on transite sheeting	Tape on seams	Transite wall panels

Vrooman Center (VRO)

NOTE: Building wide abatement has been completed to remove all ACM materials. If insulation materials other than fiberglass or armaflex (foam) are discovered in mechanical rooms, pipe chases, above ceilings or behind walls, stop work and contact the ISU Project Manager.

Watterson Dining Commons (WDC)

NOTE: Building wide abatement has been completed to remove all ACM materials. If insulation materials other than fiberglass or armaflex (foam) are discovered in mechanical rooms, pipe chases, above ceilings or behind walls, stop work and contact the ISU Project Manager.

Watterson Towers North and South (WTN/WTS)

Homogenous Area	Description	Location
Fitting insulation	Hard mud material on fiberglass, tar paper, and foam insulated piping	Mechanical rooms, pipe chases, above ceilings, behind walls, exposed areas
12x12 floor tile	“older” 12”x12” floor tile, gray/black, beige/gray/black/tan	Stairwells and stair well landings, formal areas, basement areas and some student rooms
9x9 tile	“older” 9”x9” floor tile, tan/black/streaked	Stairwells and stair well landings, formal areas, basement areas and some student rooms

Tri Towers/West Campus

Haynie Hall (HAY), Wilkins Hall (WIL), Wright Hall (WRT)

Homogenous Area	Description	Location
Layered paper pipe insulation	Cardboard like paper insulation on piping	Mechanical rooms, pipe chases, ceiling spaces, behind walls and on exposed piping
Fitting insulation	Hard mud like insulation on pipe fittings on layered paper and fiberglass insulated piping	Mechanical rooms, pipe chases, ceiling spaces, behind walls and on exposed piping.
Tank insulation	Insulation on tanks and pressure vessels	Mechanical rooms

NOTE: substantial abatement work has been completed in all 3 buildings and most materials have been removed. However, caution should be used when accessing areas above ceilings and behind walls as some materials may not have been accessible during abatement project work.

Williams Hall (WIH)

Homogenous Area	Description	Location
Aircell pipe insulation	Cardboard like insulation on piping and ductwork	Mechanical rooms, pipe/duct chases, above ceilings, behind walls, openly exposed
Mag block pipe insulation	Hard, white insulation on piping	Mechanical rooms, pipe/duct chases, above ceilings, behind walls, openly exposed
Fitting insulation	Hard fitting insulation material on fiberglass, mag block, and air cell insulated piping	Mechanical rooms, pipe chases, above ceiling, behind walls, openly exposed

Breeching insulation	Insulation on boilers and other pressure tanks and HVAC equipment	Mechanical rooms
Spray on acoustical ceiling	Textured finish on ceiling plaster	315 suite
Transite	Concrete like sheeting	Mechanical rooms and room 225A
9x9 and 12x12 floor tile	Older 9"x9" and 12"x12" floor tile, beige, tan, burnt red, black, green, gray	Throughout building
Floor tile mastic	Black mastic under older 9"x9" and 12"x12" floor tile	Throughout building